

## **Bubbling on Recording Side of DVD When Printing on Certain Brands of DVD Media – How to Fix**

Bubbling occurs on the recording layer very intermittently with various brands of DVD-R Everest Printable Media. Bubbling can be seen where the clamp pins press against the disc as seen in the following picture.



New clamping pins are now available that can be easily replaced in a matter of minutes. The P/N # is 203383-002 and the price is \$8.10 per pin and should be ordered in sets of two.

To order call:

Advanced World Products  
(510) 226-9062