

# DISKETTE DUPLICATION EQUIPMENT PRICE LIST

Updated 11/1/2018 - AWP (510) 226-9062

**Refurbished Equipment** = Used, Good condition. Worn parts replaced, includes new copy drive. Also includes on-going service, support, 1 Year Warranty on the system and 1 YR or 20,000 copies Copy Drive Warranty.

## TRACER/ST STANDALONE 3.5" DISKETTE DUPLICATORS

PRODUCT	PRICE(\$)
---------	-----------

<a href="#">Tracer/ST Model 223R</a>	\$5,500
--------------------------------------	---------

-Copies 137/hr 720K/1.44Mb (**Refurbished**)

-Includes Refurbed Autoloader, New Copy Drive, Hoppers, Power Cord, ST Owner's Manual, Quick Start Guide

### TRACER/ST OPTIONS - ACCESSORIES

540 Mb Hard Disk Drive	\$595
3.5" AAD Alignment Disk	\$90
<a href="#">Loader &amp; Drive Cleaning Kit</a>	\$35
<a href="#">3.5" Cleaning Diskette</a>	\$10

TRACER/ST MANUALS (PDF Download)

[Tracer/ST Service Manual - 147 pages \(\\$40\)](#)

[Tracer/ST 6000 Owner's Manual - 176 pages \(\\$35\)](#)

[Tracer/ST 223 Owner's Manual - 156 pages \(\\$35\)](#)

[Tracer/ST 8000 Owner's Manual - 210 pages \(\\$35\)](#)

\*Refurbished=Worn parts are replaced and comes with a 1 Year warranty for system.

- Copy Drive is NEW.

- Drive Warranty - Electronics = 1 Year.

- Drive Warranty - Mechanical (ie., heads, motor, chucking pin, etc.)= 1 Year or 20,000 copies, whichever comes first.

- Mechanical Drive Warranty voided by any damage caused by user's media (ie., head ripped off drive due to bent 3.5" disk shutter, etc.)

- Extended warranties available. Costs depends on level of service. Call for pricing.

---

## REFURBISHED PC BASED DUPLICATION SYSTEMS

<a href="#">Tracer 3+ Standard System</a>	\$4,200
---	---------

-Tracer 3+ Autoloader (**Refurbished**)

-PC Trace Pro Software

-Single Speed 300 RPM Copy Drive

-100 disk input/output capacity

-Drive A: or B: Cable Set

-Duplicates 30+/hr 1.44Mb Disks/hr.

-1 Year Warranty (copy drive = 30 days)

\*Refurbished=Worn parts are replaced and comes with a 1 Year warranty for system, 30 days on copy drive. Drive, software, controller and cables are new.

ALL REFURBISHED EQUIPMENT IS AVAILABLE ON A FIRST-COME FIRST-SERVED BASIS AND THERE IS NO GUARANTEE MADE ON AVAILABILITY. PLEASE CALL FOR CURRENT AVAILABILITY.

---

## PERIPHERALS

[DL-3000 Automatic Disk Labeler \(Refurbished\)](#) \$3,999

-Labels flat or wrap around labels with no adjustments. Labels 3,200 disk/hr wrap or flat.

DL3000 User & Service Manual (PDF Download)

[DL3000 User/Service Manual \(35 pages\)](#) \$25

---

## TRACE REPAIR/PARTS PRICING

Labor Rate: \$150.00/hr.  
Trace Drive Tune-up: \$125.00 (includes labor)  
Trace Minor Loader Tune-up: \$550.00 (includes labor & basic parts (ie., belt, pulley, rollers, O-Rings).  
Trace Loader Major Tune-up: \$999.00 (Same as Minor + Complete tear down of autoloader to remove and clean all diskette transfer roller bearings.)

Tracer ST 223/6000 Base Drive Replacement: \$625.00

Trace Orange Drive Belt: \$20.00

Base Drive Replacements include:

- Old Base Drive is removed and replaced with a **Brand New Base Drive.**
- New Base Drive is tuned to the drive electronics board: Includes optimizing Read/Write Asymmetry, Window Margin, Index-to-data, Amplitude, and Drive Alignment.
- Drive comes with a Data Test sheet that shows all test parameter values and drive must pass all tests. [Data Sheet Test Example.](#)
- Drive Life Counter is reset to 0 and then as a final test the drive must duplicate 25 disks without any failures and a maximum of 3 retries total for all 25 copies.
- New Base drive includes a 1 Year or 20,000 Copy Warranty, whichever comes first.

*(Applicable shipping, tax and handling are additional to above prices)*

RETURN POLICY - DISK DUPLICATION PERIPHERALS MAY BE RETURNED WITHIN 30 DAYS WITH NO RESTOCKING FEE IF EQUIPMENT DID NOT PERFORM AS ADVERTISED (IE., DID NOT COPY THE FORMATS YOU NEEDED, PROBLEMS WITH SYSTEM, ETC.).

EQUIPMENT TO BE RETURNED WITHOUT A VALID REASON WILL BE SUBJECT

TO A 20% RESTOCKING FEE. ALL EQUIPMENT RETURNED SHOULD INCLUDE ALL ORIGINAL

PACKING MATERIALS AND EQUIPMENT SHOULD BE IN SAME CONDITION AS WHEN PURCHASED.